



Republic of the Philippines
Department of Transportation and Communications
LAND TRANSPORTATION FRANCHISING & REGULATORY BOARD
East Avenue, Quezon City

MEMORANDUM CIRCULAR
NUMBER 2015-010

Subject: CLARIFICATION OF MEMORANDUM CIRCULAR NO. 2015-004

On January 26, 2015, the Board issued Memorandum Circular (MC) No. 2015-004 prescribing the minimum dimension, safety and comfort features for proposed Taxi Service compact sedan units.

So as to avoid confusion on the interpretation and application of Item A-2 of the said MC, the Board hereby clarifies that the piston displacement of 1200 cc for Item A-2 is the minimum piston displacement requirement and not necessarily the exact displacement. Sedans with engine displacements higher than 1200 cc are allowed for acceptance as proposed substitute units provided the dimensions thereof are equal to or more than the dimensions listed under sub-paragraphs 2.1, 2.2, 2.3 and 2.4 of said MC. It is also understood that sedans with engine displacement higher than 1200 cc shall have a life span of thirteen (13) years.

All other issuances or parts thereof inconsistent herewith are hereby modified, amended or superseded accordingly.

This Memorandum shall take effect immediately after its publication in a newspaper of general circulation. Let three (3) copies hereof be filed with the UP Law Center pursuant to Presidential Memorandum Circular No. 11 dated October 9, 1992.

SO ORDERED.

MAR 19 2015

Quezon City, Metro Manila.

EFFECTIVITY DATE: 20 MAR 2015


Atty. WINSTON M. GINEZ, CPA
Chairman




Engr. RONALDO F. CORPUS
Board Member


Atty. ANTONIO ENRILE-INTON, JR.
Board Member

Attested by:


ATTY. ROBERTO P. CABRERA III
Executive Director

